

VIA FEDERAL EXPRESS

AT&T

131 Morristown Road
Basking Ridge, NJ 07920

December 20, 1991

109990


Mr. Michael Towle (3HW21)
Remedial Project Manager
U.S. Environmental Protection Agency
Region III
841 Chestnut Building
Philadelphia, PA 19107

RE: Monthly Inspection
C & D Recycling Site
Foster Township, PA

Dear Mike:

Enclosed is the monthly inspection and maintenance report for the
C & D Recycling Site.

Sincerely,



Joe Chikowski
Senior Engineer

JTC/mhl

Enclosure

AR401147

B. E. S.

ENVIRONMENTAL SPECIALISTS INC.

And 24-Hour Emergency Response

P.O. BOX 1830

KINGSTON, PENNSYLVANIA 18704-0830

Phone: (717) 779-5316

December 10, 1991

A T & T Corporation
131 Morristown Road Room B-2173
Basking Ridge, New Jersey 07920


Attention: Joseph T. Chikowski

Dear Mr. Chikowski:

Enclosed please find the completed copy of the site inspection report for the December site visit to the C & D Recycling site. All maintenance and corrective activities performed during this site inspection have been listed.

Once again, thank you for your continued interest in the quality field services provided by B.E.S. Environmental Specialists, Inc.

Yours truly,



Lydia Hirner

enc.

C&D RECYCLING SITE

MONTHLY INSPECTION AND MAINTENANCE REPORT

SECTION I - General

1. Name of company performing inspection:
B.E.S. Environmental Specialists, Inc.
2. Name of inspector(s):
Allen Gromel
Donald Ogin
3. Beginning date of this inspection:
December 6, 1991
4. Site map reviewed?
Yes
5. Previous Inspection and Maintenance Report reviewed?
Yes
6. Date of previous inspection:
November 6, 1991
7. Were any maintenance activities required on previous inspection report in which corrective action was not taken? No If so, which activities were not completed?

AR401149

SECTION II - FIELD INSPECTION

{A site map must be taken to the site.}

1. Site Security Fence: Walk perimeter/Note location of deficiencies on Site Map.

- o Warning signs intact? Yes X No If not, action taken:
- o Chain link fence intact? Yes X No If not, action taken:
- o Barbed wire intact? Yes X No If not, action taken:
- o Gates intact? Yes X No If not, action taken:
- o Tension wire intact? Yes X No If not, action taken:
- o Chain and padlocks intact? Yes X No If not, action taken:
- o Additional observations [erosion under fence, loss of post support, etc.]

AR601150

2. Temporary Ash Cover: Inspect all three piles individually.

Northern Pile

- o Plastic cover intact? Yes X No If not, action taken:
- o Tire hold-down intact? Yes X No If not, action taken:
- o Perimeter drainage channel intact? Yes X No
If not, action taken:
- o Additional observations:

Central Pile

- o Plastic cover intact? Yes No X If not, action taken: **Pile was recovered**
- o Tire hold-down intact? Yes X No If not, action taken:
- o Perimeter drainage channel intact? Yes X No
If not, action taken:
- o Additional observations:

Southern Pile

- o Plastic cover intact? Yes No X If not, action taken: **Pile was recovered**
- o Tire hold-down intact? Yes X No If not, action taken:
- o Perimeter drainage channel intact? Yes X No
If not, action taken:
- o Additional observations:

3. Drainage Channel: Walk entire length/Note locations of deficiencies on Site Map.
- o Riprap layer intact? Yes ☒ No ☐ If not, action taken:
 - o Geotextile intact? Yes ☒ No ☐ If not, action taken:
 - o Subgrade providing adequate support to bottom and sideslopes? Yes ☒ No ☐ If not, action taken:
 - o Channel unobstructed? Yes ☐ No ☒ If not, action taken: **Channel cleared**
 - o Additional observations:
4. Silt Fence: Walk all reaches/Note location of deficiencies on Site Map.
- o Silt Fence intact? Yes ☒ No ☐ If not, action taken:
 - o Fabric secured to posts? Yes ☐ No ☒ If not, action taken: **Fabric was re-secured to posts**
 - o Fabric entrenched into soil? Yes ☒ No ☐ If not, action taken:
 - o Runoff flowing through fence and not around the fence? Yes ☒ No ☐ If not, action taken:
 - o Additional observations:

5. CMP Drainage Pipe Downdrain: Walk entire length/Note locations of deficiencies on Site Map.

- o Pipe connections intact? Yes X No If not, action taken:
- o Anchor bars embedded and intact? Yes X No If not, action taken:
- o Outlet area intact? Yes No X If not, taken: **Reattached anchor bars to outlet**
- o Pipe outlet unobstructed? Yes No X If not, action taken: **Outlet cleared**
- o Additional observations:

SECTION III - Summary

1. Date Inspection and Maintenance Activities were completed: December 9, 1991
2. List maintenance activities not completed at the time this report was completed:
3. Additional observations:

Allen Gromel
{Name of Inspector}

Allen Gromel
{Signature}

December 9, 1991
{Date}

AR601154

APPROX LOCATION
OF NORTHERN
ASH PILE
(COVERED)

EXISTING
FENCE

EXISTING
BUILDING

EXISTING
PARKING
AREA

EXISTING
ABANDONED
HOUSE

EXISTING
BARN

EXISTING
BARN

APPROXIMATE LOCATION
UPGRADED CHANNEL

APPROX. LOCATION
OF SOUTHERN
ASH PILE
(COVERED)

APPROX. LOCATION OF
CENTRAL
ASH PILE
(COVERED)

APPROX. LOCATION OF
EQUIPMENT WASHPAD

APPROX LOCATION OF
8" DIA. CORRUGATED
METAL PIPE DOWN
DRAIN

SHALE PIT

AR401155